




**SECURIT GUARD**

113 West G Street  
#5044  
San Diego California 92101  
United States of America (the)



**C14th & Commercial (C14)**  
**One 14th St.**  
**San Diego California 92101**  
**United States of America (the)**

Incident Report	
Report #	1795143
Report Date	04/14/2025
Report Time	11:13am
Created By	Jaasiel Lopez Escobar #11056
Position	Onsite Guard x1.75
Client	C14th & Commercial (C14)

Please Choose Incident	
<b>Elevator / Other</b>	
Please Provide In Detail What Incident Occured (Eg. WHO, WHAT, WHERE and HOW)	Special request
	 <p>A full resolution version of this image is included in the printed report as well as stored on the platform.</p>
	 <p>A full resolution version of this image is included in the printed report as well as stored on the platform.</p>
Area Of Incident	
Second Picture of Incident	
Surrounding Area Of Incident	 <p>A full resolution version of this image is included in the printed report as well as stored on the platform.</p>

**SECURIT GUARD**  
 113 West G Street  
 #5044  
 San Diego California 92101  
 United States of America (the)



**C14th & Commercial (C14)**  
**One 14th St.**  
**San Diego California 92101**  
**United States of America (the)**

OLD REPORT USE NEW REPORT!!! Incident Report - St Teresa C14	
Report #	1718335
Report Date	02/26/2025
Report Time	05:39pm
Created By	Michael Trejo #11125
Position	Onsite Guard x1.75
Client	C14th & Commercial (C14)


**Incident Report**

Incident  
 Area of incident  
 TIME THAT THE INCIDENT OCCURED  
 Provide detailed report of Incident and with above information (Eg. WHO, WHAT, WHEN, WHERE, HOW and UNIT NUMBER)

**Elevator / Other**  
 Lobby  
 05:15pm

The elevator mechanic just left the building and he said he got 2 elevators working and they will come back tomorrow to keep working on the elevators. I asked and he said he will inform Tony the maintainance guy.

Area Of Incident




A full resolution version of this image is included in the printed report as well as stored on the platform.

Second Picture of Incident



A full resolution version of this image is included in the printed report as well as stored on the platform.

Surrounding Area Of Incident



A full resolution version of this image is included in the printed report as well as stored on the platform.

**SECURIT GUARD**

113 West G Street  
#5044  
San Diego California 92101  
United States of America (the)



**C14th & Commercial (C14)**  
**One 14th St.**  
**San Diego California 92101**  
**United States of America (the)**

Incident Report	
Report #	1677399
Report Date	01/29/2025
Report Time	09:59am
Created By	Philip Lawton #10931
Position	Onsite Guard x1.75
Client	C14th & Commercial (C14)

Please Choose Incident

**Elevator / Other**


Please Provide In Detail What Incident Occured (Eg. WHO, WHAT, WHERE and HOW)

Area Of Incident


Second Picture of Incident

Surrounding Area Of Incident


Please get all three cameras back working In the elevators for tracking trespassers



A full resolution version of this image is included in the printed report as well as stored on the platform.



A full resolution version of this image is included in the printed report as well as stored on the platform.





A full resolution version of this image is included in the printed report as well as stored on the platform.




**C14th & Commercial (C14)**  
**One 14th St.**  
**San Diego California 92101**  
**United States of America (the)**

Incident Report	
Report #	1527161
Report Date	10/17/2024
Report Time	08:38am
Created By	Delaney Gonzalez #10852
Position	Onsite Guard x1.75
Client	C14th & Commercial (C14)

Please Choose Incident	<div style="border: 1px solid red; padding: 2px; display: inline-block;">Elevator / Other</div>
Please Provide In Detail What Incident Occured (Eg. WHO, WHAT, WHERE and HOW)	<p>At around 8:00am</p> <p>Juanita one of the cleaning ladies came down to the lobby and stated that she and her worker cleaning lady got stuck on the elevator on the cart 3 that doesn't have camera. As I didn't know because without having the camera for me to see it's hard to know when the elevator is stuck and stops working as we had many incidents with people inside waiting for help. When Juanita was inside she stated that she tried to call Tony maintenance and the front desk phone as was your inside the elevator there's bad service and calls and text don't go thru. She also stated that the elevator stopped working for 5min and started moving to the 6th and 7th floor very fast and came down fast to the 1st floor as she stated like it felt that it was going to drop the way it was going very fast. I talked to Tony that the camera needs to be fixed as that's the only way that we will be able to see the inside of the elevator and we will notice when there's an issue again.</p>
Area Of Incident	 <p>A full resolution version of this image is included in the printed report as well as stored on the platform.</p>
Second Picture of Incident	 <p>A full resolution version of this image is included in the printed report as well as stored on the platform.</p>

Surrounding Area Of Incident



A full resolution version of this image is included in the printed report as well as stored on the platform.

**SECURIT GUARD**

113 West G Street  
#5044  
San Diego California 92101  
United States of America (the)



**C14th & Commercial (C14)**

**One 14th St.**  
**San Diego California 92101**  
**United States of America (the)**

Incident Report	
Report #	1515569
Report Date	10/11/2024
Report Time	01:17pm
Created By	Delaney Gonzalez #10852
Position	Onsite Guard x1.75
Client	C14th & Commercial (C14)

**Incident Report**

Please Choose Incident

**Elevator / Other**

Please Provide In Detail What Incident Occured (Eg. WHO, WHAT, WHERE and HOW)


Here's a more polished version of your report:

At 12:55 PM

As I exited the bathroom and was walking toward the front desk, I heard a knocking noise. I rushed to check the cameras, as it sounded like someone might need help near the garage. Upon checking, I saw no one in the area. When I zoomed in on the elevator cameras, I noticed that the right-side elevator, Cart 3, was stuck on the first floor with the doors closed. Samuel was trying to force the doors open from the outside, but I couldn't see the computer system, as the camera for that elevator isn't working, preventing us from receiving an immediate alert.


I contacted Tony from maintenance, who quickly went to the 15th floor to reset the elevator. Once reset, the elevator started moving, and I saw residents exiting on the 3rd floor. The residents are safe, and the elevator is functioning properly again. However, the camera for Cart 3 needs to be repaired, as it creates a security blind spot, making it difficult to monitor in case of future incidents.

Area Of Incident



A full resolution version of this image is included in the printed report as well as stored on the platform.

Second Picture of Incident



A full resolution version of this image is included in the printed report as well as stored on the platform.

Surrounding Area Of Incident



A full resolution version of this image is included in the printed report as well as stored on the platform.

**SECURIT GUARD**

113 West G Street  
#5044  
San Diego California 92101  
United States of America (the)



**C14th & Commercial (C14)**

**One 14th St.**  
**San Diego California 92101**  
**United States of America (the)**

Incident Report	
Report #	1472649
Report Date	09/16/2024
Report Time	09:28pm
Created By	George Guerrero #10978
Position	Onsite Guard x1.75
Client	C14th & Commercial (C14)

Please Choose Incident

**Elevator / Other**

Please Provide In Detail What Incident Occured (Eg. WHO, WHAT, WHERE and HOW)


Officer owens had me to watch this drunk man to make sure hes ok.. but the gentle men so completely drunk. I yold him to leave but didn't want to. He tried to get into the elevator but he was to intoxicated he slipped n fell on the floor while officer owens was walking up to escort thee drunk man to his unit

Area Of Incident



A full resolution version of this image is included in the printed report as well as stored on the platform.

Second Picture of Incident



A full resolution version of this image is included in the printed report as well as stored on the platform.